



Honed Marble Cleaning Treatment & Maintenance.

www.stratatiles.co.uk

The purpose of this document is to explain the use and application methods for FILA products and the tools necessary for the best routine maintenance (every day) and extra maintenance (periodically as needed).

strata
tiles



Initial Cleaning

The initial washing is necessary to remove the residue of the grout and to prepare the floor for the treatment with the impregnator.

Product	CLEANER PRO* diluted 1:30
Equipment	Single-disc professional cleaner fitted with a white pad; floor cloth or mop
Procedure	Proceed by applying the solution over the floor, leave to act for five minutes and then work over the surface with a single disc professional cleaner with a white pad. Use a cloth or 'aqua vac' to remove residues and then rinse thoroughly with clean water.
Coverage	1 liter for 50 m ²

Protecting Indoor Floors

Product	MP 90 ECO XTREME*
Equipment	Brush or fleece pad clean dry lint free cotton cloth
Procedure	Apply an even coat of FILA MP90 ECO PLUS* to the surface with a brush or cloth. Remove the excess after 4 hours, using a cloth soaked in the product to make sure the application is uniform and remove any unabsorbed excess.
Coverage	1 liter for 20 -30 m ² approx.

*To maintain optimal the treatment we advise to evaluate the re-application of **FILA MP90 ECO PLUS*** at least every 2-3 years, on a dry and clean surface.

Routine Maintenance

Product	CLEANER PRO* diluted 1:200/ 25 ml in 5 litres of water
Equipment	Single-disc professional cleaner fitted with a white pad; floor cloth or mop
Procedure	For routine maintenance, dilute Fila CLEANER PRO* in water 1:200. Clean surface with a clean mop, cloth or a single disc cleaning machine. At this dilution rinsing is not necessary.
Coverage	1 liter for 1500 m ²

Extra Maintenance

Product	CLEANER PRO* diluted 1:30
Equipment	Single-disc professional cleaner fitted with a white pad; floor cloth or mop
Procedure	Proceed as for the initial clean by applying the solution over the floor, leave to act for five minutes and then work over the surface with a single disc professional cleaner with a white pad. Use a cloth or 'aqua vac' to remove residues and then rinse thoroughly with clean water.
Coverage	1 liter for 50 m ²